

Affected Products of Express5800 Series (100 Series)

Nov 25, 2019

Product name: Express5800/	Shipping status	Scheduled date of BIOS release* for INTEL-SA-00213/-00223/-00233
D120h	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later included in BIOS F24 or later> SA-00223/SA-00233:affected<BIOS: F33 or later>
E120g-M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E120f-M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E120e-M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E120d-M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E120d-1	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E110d-M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
Rack Server		
R120h-2M	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later> SA-00223/SA-00233:affected<BIOS: v2.04 or later>
R120g-2M	Shipping stopped	SA-00233:affected<BIOS: 5.0.9025 or later>
R120f-2M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120e-2M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120d-2M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120h-2E	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later> SA-00223/SA-00233:affected<BIOS: v2.04 or later>
R120g-2E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120f-2E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120e-2E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120d-2E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120h-1M	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later> SA-00223/SA-00233:affected<BIOS: v2.04 or later>
R120g-1M	Shipping stopped	SA-00233:affected<BIOS: 5.0.9025 or later>
R120f-1M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120e-1M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120d-1M	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120h-1E	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later> SA-00223/SA-00233:affected<BIOS: v2.04 or later>
R120g-1E	Shipping stopped	SA-00233:affected<BIOS: 5.0.9025 or later>
R120f-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120e-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R120d-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R110j-1	Being shipped	SA-00213:affected <SPS FW: Being investigated> SA-00223/SA-00233:affected<BIOS: v1.22 or later>
R110i-1	Being shipped	SA-00213:affected <NM FW: 4.1.4.54 or later> SA-00223/SA-00233:affected<BIOS: Jan. 2020> SA-00213:affected <NM FW: 4.1.4.54 or later>
R110h-1	Shipping stopped	SA-00223/SA-00233:affected<BIOS: Being investigated>
R110g-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R110f-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R110e-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
R110d-1E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
E110d-1	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
Tower Server		
T120h	Being shipped	SA-00213:affected <SPS FW: 4.0.4.393 or later> SA-00223/SA-00233:affected<BIOS: v2.04 or later>
T120g	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T120f	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T120e	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T120d	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T110j-S	Being shipped	SA-00213:affected <SPS FW: 5.0.4.027 or later included in BIOS F12 or later> SA-00223/SA-00233:affected<BIOS: F12 or later>
T110i-S	Being shipped	SA-00213:affected <NM FW: 4.1.4.54 or later> SA-00223/SA-00233:affected<BIOS: Jan. 2020>
T110h-S	Being shipped	SA-00213:affected <NM FW: 4.1.4.54 or later> SA-00223/SA-00233:affected<BIOS: Being investigated>
T110g-S	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T110f-S	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T110j	Being shipped	SA-00213:affected <SPS FW: 5.0.4.027 or later included in BIOS F12 or later> SA-00223/SA-00233:affected<BIOS: F12 or later>
T110i	Being shipped	SA-00213:affected <NM FW: 4.1.4.54 or later> SA-00223/SA-00233:affected<BIOS: Jan. 2020> SA-00213:affected <NM FW: 4.1.4.54 or later>
T110h	Being shipped	SA-00223/SA-00233:affected<BIOS: Being investigated>
T110g-E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
T110f-E	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
GT110e	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
GT110e-S	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
GT110d	Shipping stopped	SA-00233:affected<BIOS: Being investigated>
GT110d-S	Shipping stopped	SA-00233:affected<BIOS: Being investigated>

After the system BIOS is published, the download information will be described on this list.

*Note for applying BIOS update:
Before obtaining and applying BIOS update , please make sure to check the BIOS version of the product you use, and apply the