
N8104-184 Dual Port 10GBASE-T Adapter

Notes on Firmware Updating

When the N8104-184 firmware is updated, an error may occur in the "Step3 Deployment" step depending on the server model. See below for the message. Even if the error message appears, ignore the message because the firmware has been updated correctly.

[Messages]

Component:	<code>firmware-nic-intel-1.19.11-1.1.x86_64</code>
Package:	<code>HPE Intel Online Firmware Upgrade Utility for Linux x86_64</code>
Deployment status:	<code>Update returned an error</code>
View Log:	<code>Return code: 7</code>