

---

## **Supplement of Using R120h-1E/R120h-2E/T120h onboard network adapter or N8104-193/194/195 on Windows Server**

---

When using the onboard network adapter of R120h-1E/R120h-2E/T120h, N8104-193/194/195 on Windows Server, installing Starter Pack at the server, the event log below may be recorded.

This event does not affect system operation.

**Level : Warning**

**Source : i40eb**

**ID:69**

**HPE Ethernet xGb x-port xxxx Adapter**

**The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.**

\* "x" depends on the system environment.

**Level : Warning**

**Source : i40eb**

**ID:101**

**HPE Ethernet xGb x-port xxxx Adapter**

**PROBLEM: Flow Control disabled on this interface. For RDMA traffic, it is recommended that flow control be enabled end to end on all network interfaces and switches to avoid performance degradation from dropped packets.**

**ACTION: Enable link level flow control or priority flow control for network direct port 445 on this interface.**

\* "x" depends on the system environment.

**Level : Warning**

**Source : i40ei65**

**ID:69**

**The description for Event ID 69 from source "i40ei65" cannot be found.**

**Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.**