
N8104-175	Dual Port 10GBASE-T LOM Card
-----------	------------------------------

N8104-184	Dual Port 10GBAS-T Adapter
-----------	----------------------------

Notes on Firmware Updating

When the N8104-184 or N8104-175 firmware is updated, an error may occur in the "Step3 Deployment" step depending on the server model. See below for the message. Even if the error message appears, ignore the message because the firmware has been updated correctly.

[Messages]

Component:	firmware-nic-intel-1.22.50-1.1.x86_64
Package:	HPE Intel Online Firmware Upgrade Utility for Linux x86_64
Deployment status:	Update returned an error
View Log:	Return code: 7