
Starter Pack (ver. S8.10-010.08)

Unable to update RAID controller firmware 5.61

[Products]

N8103-189/190/191/192/193/194/195/196/201 RAID controller

If your RAID controller firmware version is less than 5.32 (1.05 / 1.34 / 1.65 / 1.98 / 1.99 / 2.62 / 2.65 / 3.00 / 4.11 / 5.00), you can use this Starter Pack (ver. S8.10-010.08) is not enough to update to firmware 5.61.

After applying this Starter Pack (ver. S8.10-010.08), update to firmware 5.61 using one of the following methods:

- (1) Let this Starter Pack (ver. S8.10-010.08) apply again.
- (2) Apply firmware 5.61 according to the contents of the following URL.
<https://www.58support.nec.co.jp/global/download/084075-G02/index.html>

[Supplement]

- If you are using R110j-1, you can only update by the method (2).
- If you are using firmware 5.32, you do not need to execute the above method, and this Starter Pack (ver. S8.10-010.08) can be updated to firmware 5.61.