
Supplement of Using R120h-1E/R120h-2E/T120h onboard network adapter or N8104-193/194/195 on Windows Server

When using the onboard network adapter of R120h-1E/R120h-2E/T120h, N8104-193/194/195 on Windows Server, installing Starter Pack at the server, the event log below may be recorded.

This event does not affect system operation.

Level : Warning

Source : i40eb

ID:69

HPE Ethernet xGb x-port xxxx Adapter

The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.

* "x" is a different display name depending on the LAN board.

Level : Warning

Source : i40eb

ID:101

HPE Ethernet xGb x-port xxxx Adapter

PROBLEM: Flow Control disabled on this interface. For RDMA traffic, it is recommended that flow control be enabled end to end on all network interfaces and switches to avoid performance degradation from dropped packets.

ACTION: Enable link level flow control or priority flow control for network direct port 445 on this interface.

* "x" is a different display name depending on the LAN board.

Level : Warning

Source : i40ei65

ID:69

The description for Event ID 69 from source "i40ei65" cannot be found.

Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.

Level : Warning

Source : i40ei68

ID:69

HPE Ethernet xGb x-port xxxx Adapter

The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.

*** "x" is a different display name depending on the LAN board.**