

---

## **Supplement of Using R120h-1E/R120h-2E/T120h onboard network adapter or N8104-193/194/195**

### **on Windows Server 2012 R2, Windows Server 2016 and Windows Server 2019**

---

When using the onboard network adapter of R120h-1E/R120h-2E/T120h, N8104-193/194/195 in Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019, the event log below may be recorded, and you can ignore these event because these are temporary events.

**Level : Warning**

**Source : i40eb**

**ID:69**

**HPE Ethernet xGb x-port xxxx Adapter**

**The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.**

\*"x" depends on the system environment.

**Level : Warning**

**Source : i40ei65**

**ID:69**

**The description for Event ID 69 from source "i40ei65" cannot be found.**

**Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.**