# N8116-51/83/84(SAS-expander)

## Notes on Firmware Updating

When updating firmware from this Starter Pack (Ver S8.10-009.01), please do NOT apply the following firmware update module (Ver.5.08).

## [Package Name]

Supplement Upate / Online ROM Flash Component for Linux (x64) – HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers (firmwaresmartarray2de15b6882-5.08-1.1x86\_64)

## 1. On Windows

Follow the procedure shown in "2.On other Operationg System (VMware ESXi) or Offline Mode" to perform the firmware update by applying offline.

If using "Integrated Installation" after the OS after installation, the firmware of the SAS expander card will be forcibly updated to Ver5.08. After applying by using "Integrated Installation", please apply Ver4.22 according to the procedure described below.

[SAS-expander firmware Ver4.22]

https://www.58support.nec.co.jp/global/download/N8116-51\_83\_84

## 2. On other Operating System (VMware ESXi) or Offline Mode


When applying the update according to "Using offline mode", the following packages are "Selected" when you follow the inventory procedure.

Please deselect it and change it so that Ver5.08 is not applied.

## [Inventory screen image]



Click "Selected" or "Forced" to change it to "Select" or "Force"



## [Firmware Ver4.22 offline application procedure]

If application of firmware Ver4.22 needed, please apply it individually from Starter Pack Version S8.10-008.01.

[Starter Pack Version S8.10-008.01] http://www.58support.nec.co.jp/global/download/starterpack/810/008/01/index.html

## [Package Name]

Supplement Upate / Online ROM Flash Component for Linux (x64) – HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers (firmwaresmartarray2de15b6882-4.22-1.1x86\_64)

## [Inventory screen image]



Click "Select" or "Force" to change it to "Selected" or "Forceed"

