
Supplement of Using N8104-177/183/187 on Windows Server

When using the N8104-177/183/187 on Windows Server, installing Starter Pack at the server, the event log below may be recorded.

This event does not affect system operation.

Level: Warning

Source: qebdrv

ID : 56

NTPNP_PCIxxxx: RDMA has been implicitly disabled due to RDMA interface incompatibility between NDIS Miniport (ver x.xx.xx.x) and VBD (ver x.xx.x.x) drivers. VBD driver upgrade is required.

* "x" depends on the system environment.

Level: Warning

Source: l2nd2

ID : 38

HPE Ethernet xGb x-port xxxx Adapter : NDIS-Miniport is not ompatible(older or newer) with bus driver. Hence only basic L2 functionality is available.

* "x" depends on the system environment.