
Supplement of Using N8104-176/186 on Windows Server

When using the N8104-176/186 on Windows Server, installing Starter Pack at the server, the event log below may be recorded.

This event does not affect system operation.

Level : Warning

Source : i40ea

ID:69

HPE Ethernet xGb x-port xxxx Adapter

The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.

* "x" depends on the system environment.

Level : Warning

Source : i40ei

ID:69

The description for Event ID 69 from source "i40ei" cannot be found.

Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.

Level : Warning

Source : i40ei65

ID:69

The description for Event ID 69 from source "i40ei65" cannot be found.

Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.