

---

## **Caution of Wake on LAN feature on N8104-173 (Dual Port 10GBASE-T LOM Card)**

---

After applying the Firmware version 7.18.26 in the Starter Pack (Ver S8.10-007.01) to N8104-173(Dual Port 10GBASE-T LOM Card), use PORT1 for Wake on LAN feature.

Wake on LAN feature with a PORT2 may not work depending on hardware environment.