
N8103-237/238 RAID Controller Notes

When the OS is VMware ESXi, please use firmware 03.01.14.062 applied by this Starter Pack (Ver.S8.10-010.06).

When the OS is anything other than VMware ESXi, please change firmware to 03.01.17.056 after applying this Starter Pack (Ver.S8.10-010.06). Please check the contents of the following URL and change the firmware. For the change procedure, please refer to the included procedure manual.

<N8103-237/238 RAID controller firmware modules 03.01.17.056>

<http://www.58support.nec.co.jp/global/download/N8103-237/index.html>