
N8103-237/238 RAID Controller Notes

When the OS is VMware ESXi, please use firmware 03.01.14.062 applied by this Starter Pack. When the OS is anything other than VMware ESXi, please change firmware to 03.01.17.056 after applying this Starter Pack. Please check the contents of the following URL and change the firmware. For the change procedure, please refer to the included procedure manual.

<N8103-237/238 RAID controller firmware modules 03.01.17.056>

<http://www.58support.nec.co.jp/global/download/N8103-237/index.html>