

---

## **Supplement of Using N8104-176/186 on Windows Server**

---

When using the N8104-176/186 on Windows Server, installing Starter Pack at the server, the event log below may be recorded.

This event does not affect system operation.

**Level : Warning**

**Source : i40ea**

**ID:69**

**HPE Ethernet xGb x-port xxxx Adapter**

**The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.**

\* "x" is a different display name depending on the LAN board.

**Level : Warning**

**Source : i40ei**

**ID:69**

**The description for Event ID 69 from source "i40ei" cannot be found.**

**Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.**

**Level : Warning**

**Source : i40ei65**

**ID:69**

**The description for Event ID 69 from source "i40ei65" cannot be found.**

**Either the component that raises this event is not installed on your local computer or the installation is corrupted. You can install or repair the component on the local computer.**

**Level : Warning**

**Source : i40ei68**

**ID:69**

**HPE Ethernet xGb x-port xxxx Adapter**

**The driver for the device detected a newer version of the NVM image than expected. Please install the most recent version of the network driver.**

\* "x" is a different display name depending on the LAN board.