

**Affected Products of Express5800 Series (FT servers)****June 21, 2019**

<b>Product name: Express5800/</b>	<b>Shipping status</b>	<b>Scheduled date of BIOS release* for INTEL-SA-00213/-00223/-00233</b>
R320c	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R310c-E4	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R320d	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R310d-E4	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R320e	Being shipped	SA-00233:affected<BIOS: Being investigated>
R310e-E4	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R320f	Being shipped	SA-00233:affected<BIOS: Being investigated>
R310f-E4	Order-acceptance stopped	SA-00233:affected<BIOS: Being investigated>
R320g	Being shipped	SA-00223/00233:affected<BIOS: Being investigated>
R310g-E4	Order-acceptance stopped	SA-00223/00233:affected<BIOS: Being investigated>

After the system BIOS is published, the download information will be described on this list.

• Note for applying BIOS update:

Before obtaining and applying BIOS update , please make sure to check the BIOS version of the product you use, and apply the latest version of the BIOS update that have been released after the mitigating measure against vulnerability