Affected Products of Express5800 Series (SIGMABLADE)

Nov 25, 2019

| Product name: Express5800/ | Shipping status | Scheduled date of BIOS release* for INTEL-SA-00213/-00223/-00233 |
|----------------------------|------------------|---------------------------------------------------------------------|
| B120d | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120d-h | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120e | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120e-h | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120f | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120f-h | Shipping stopped | SA-00233:affected <bios: being="" investigated=""></bios:> |
| B120g-h | Shipping stopped | SA-00233:affected <bios: 2020="" jan,=""></bios:> |

 $After the \ system \ BIOS \ is \ published, \ the \ download \ information \ will \ be \ described \ on \ this \ list.$

• Note for applying BIOS update:

Before obtaining and applying BIOS update , please make sure to check the BIOS version of the product you use, and apply the latest version of the BIOS update that have been released after the mitigating measure against